














Sleeping barrel 4.4 x Ø2.2








1. SLEEPING BARREL- 4.4 x $\varnothing$ 2.2









No.	Detail		Pcs	
1			4	
2			1	
3			29 - 40	
4			29 - 40	
5			1	
6			1	
7			1	
8			1	
9			5	
10			1	
10.1			1	
10.2			2	
10.3			1	
11			2	
11.1			4	
11.2			2	
11.3			2	

2. SLEEPING BARREL- 4.4 x $\varnothing$ 2.2






No.	Detail		Pcs	
12			2	
13			1	
14			1	
15			1	
16			1	
17			1	
17.1			2	
17.2			1	
17.3			1	
17.4			2	
18			1	
18.1			2	
19			2	
20			2	
21			10	
22			2	
23			2	
24			2	
25			4	

3. SLEEPING BARREL- 4.4 x $\varnothing$ 2.2




No.	Detail		Pcs	
26			1	
27			16	
28			6	
29			1	
30			1	
31			1	
32			1	
33			2	
34			2	
34.1			2	
35			8	
35.1			2	
36			2	
37			2	
38			2	

4. SLEEPING BARREL- 4.4 x $\varnothing$ 2.2			
No.	Detail	Pcs	
S1		88	
S2		_____	
S3		_____	
S4		_____	
S5		2	
S6		1	
S7		_____	
S8		_____	
T1		_____	
T2		_____	
T3		1	
T4		1	
T5		2	
T6		2	
T7		_____	


5. SLEEPING BARREL- 4.4 x $\varnothing$ 2.2

No.	Detail	Pcs	
A0		—	
A1		—	
A2		—	
A3		8	
A4		60	
A5		146	
A6		20	
A7		—	
A8		32	
A9		—	
A10		—	
A11		380	
A12		—	
A13		—	
A14		—	
A15		—	
A16		—	
A17		—	
A18		1p	
A19		1p	
A20		—	


1. Sleeping barrel 4.4 x Ø2.2




2. Sleeping barrel 4.4 x Ø2.2




1



3




2




B




D




3. Sleeping barrel 4.4 x Ø2.2




1




2




3




4








5









6




4. Sleeping barrel 4.4 x Ø2.2




5. Sleeping barrel 4.4 x Ø2.2




6. Sleeping barrel 4.4 x Ø2.2




1




3




2




4




7. Sleeping barrel 4.4 x Ø2.2




1



2




3




4


A11 Pcs-12x2




8. Sleeping barrel 4.4 x Ø2.2




1



16




3



A11 Pcs-28


17



17.2


17.1

2




A4 Pcs-6

4




A11 Pcs-22










18













18.1










10. Sleeping barrel 4.4 x Ø2.2










11. Sleeping barrel 4.4 x Ø2.2



12. Sleeping barrel 4.4 x Ø2.2



13. Sleeping barrel 4.4 x Ø2.2



14. Sleeping barrel 4.4 x Ø2.2

