
Luna



Luna (List)					
No.	Detail	Pcs.	Detail code (dimention)	Instruction page No.	
1.		1	1108x2500x147	3	
2.		1	1130x2461x200	3	
3.		2	621x2613x132	3	
4.		1	Pcs. 38x240x1956 1 38x1700x663 2 38x170x1903 1	1;4	
5.		1	38x1175x2110 38x943x2110	2;3	
6.		1	60x800x1800	6;7	
7.		3	18x1090x828/805	5	
8.		2	90x566x2400	10	
9.		2	79x2461x91	10	

Luna (List)				
No.	Detail	Pcs.	Detail code (dimention)	Instruction page No.
10.		2	60x2461x91	10
11.		6	45x45x561	10
12.		4	21x845x150	9
13.		4	21x768x150	9
14.		4	21x1145x150	9
15.		2	21x1140x150	9
16.		2	21x1250x150	9
17.		4	18x76x1558	7
18.		4	18x76x866	7

Luna (List)				
No.	Detail	Pcs.	Detail code (dimention)	Instruction page No.
23.		2	18x93x1090	8
24.		2	18x93x2498	8
25.		2	45x95x2461	10
27.		2	PR0031	12
28.		1	PUS00104	12
31.		1		7
32.		4	3x1000x2534	11
33.		1	3x500x2534	11
34.		2	3x70x4000	11
35.		6	1x40x1000	11
36.		1		7

Family	Mini sleeping	barrel (List	of screws)
--------	---------------	--------------	------------

No.	Detail	Pcs.	Detail code (dimention)	Instruction page No.
1.	O-management	20	GC-4*60	2
2.		6	GC-5*100	2.1;2.2
3.	Ø-manusco	40	T-BC-4*50	7;9
4.	O-managed states and the states are the states and the states are	80	T-BC-3.5*45	4;5;6;8
5.	O-manager	8	T-GC-6*80	4
6.	Ø-manusco	800	Ng34/38	10
7.	(Virginian and Virginian and V	36	18*90	1

Luna foundation

FOUNDATION

It is very important to have a proper foundation.

Therefore we recommend making the foundation according to the sketches here.


First of all, foundation must be prepared according to the landscape and ground conditions.


The foundation under the product must be prepared specially, it must be homogeneous, tight and equal. It must be ensured that it will not change its properties. We recommend using concreate foundation. Before installation of product, we recommend to make hydro isolation of foundation.


Consult a local qualified builder or an engineer to prepare a proper foundation, which fits to your location.


Due to improper foundation, cracks in the structures may occur. Due to uneven building seating, the geometric shape of the building may change, which can result in door / window twist, or/and gap may appear. And in the worst case building's collapse.


If you do not follow recommendation, product will lose its warranty.














5. Luna

